



कार्यालय अधिशासी अभियन्ता प्रान्तीय खण्ड, लोक निर्माण विभाग, शामली



Office of the Executive Engineer, Provincial Division, P.W.D., Shamli, Uttar Pradesh
E-mail:- pdpwdshamli@gmail.com

पत्रांक 185/12
सेवा में,

दिनांक 23.06.2025


प्रबन्धक/प्रधानाचार्य
कृष्णा देवी पब्लिक स्कूल
ग्राम-गढ़ी हसनपुर, चौसाना मुण्डेट रोड़
शामली

विषय:- कृष्णा देवी पब्लिक स्कूल, ग्राम-गढ़ी हसनपुर, चौसाना मुण्डेट रोड़ शामली की नेशनल बिल्डिंग कोड 2005 के अनुसार गुणवत्ता एवं भौतिक सत्यापन के सम्बन्ध में।

सन्दर्भ:-आपका पत्रांक शून्य दिनांक 19.06.2025।

उपरोक्त विषयक सन्दर्भित पत्र के क्रम में अवगत कराना है कि आपके द्वारा प्रेषित किये गये पत्र के आधार पर अधोहस्ताक्षरी द्वारा उक्त कॉलेज का निरीक्षण किया गया, जिसका नेशनल बिल्डिंग कोड 2005 के अनुसार बिल्डिंग सेफ्टी सर्टिफिकेट सलंगन किया गया है। सामान्य परिस्थितियों में भवन सुरक्षित प्रतीत होता है। सुरक्षा मानकों का गैर अनुपालन, भवन का विस्तारीकरण, बदलाव कार्य आदि करना नियमों की अवहेलना होगी तथा वैधता स्वयं समाप्त होगी। सुरक्षा मानकों का अनुपालन, भवन का नियमित अनुरक्षण अनिवार्य है।

सलंगनक:- बिल्डिंग सेफ्टी सर्टिफिकेट।


(दीपेन्द्र जायसवाल)
सहायक अभियन्ता-प्रथम
प्रान्तीय खण्ड, लो0नि0वि0
23/06/2025 शामली

BUILDING SAFETY CERTIFICATE


No. 184 //1C-NBC(Camp-1)/25

Dated 23.06.2025

Certified that the existing building of Krishna Devi Public School at Village Garhi Hasanpur, Chausana Mundet Road, Shamli (U.P) owned/occupied by Krishna Devi Public School have complied with the building safety requirements in accordance with National Building Code Rules, and verified by the officer concerned of Provincial Division, Public Works Department, Shamli (Uttar Pradesh) on 23.06.2025 in the presence of manager Dr. Devi Singh s/o Sh. Munshi Singh and that the building/ premises is fit for occupancy with effect from 23.06.2025 for a period of Three years in accordance with rule and subject to compliance of the specific conditions as appended. Prima facie the construction of building seems to be as per norms of National Building Code rules but in case the building is not found in conformity of detailed National Building Code rules the Public Works Department shall not be held accountable.

Issued on 23.06.2025 at 02:00 PM by undersigned officers of Provincial Division, Public Works Department, Shamli.

Details of Block(s) in School	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	1/2	-	-	-	-	-


 Assistant Engineer
 Provincial Division, P.W.D
 Shamli